



Manometers

MP 100 - 101 - 105 - 112

MP 120



"Select" key
See table
"Functions available from main screen"

"Function" key

- 1x : "Hold" : measure holding
- 2x : "Min/Max" : display of minimum and maximum values from **channel 1** since last request.
- 3x : "Min/Max" : display of minimum and maximum values from **channel 2** since last request.
- 4x : Back to held measure.

"On / off" key

- ON : Switch-on
- OFF : Switch-off
- Escape : Return to previous screen














"Backlight" key

- 1x Level 1
- 2x Level 2
- 3x No backlight






























"OK" key

- 1x "To validate" or "Self-calibration" see P2.

Functions available from main screen


Self-calibration	1x  → Start self-calibration countdown
Select pressure units	1x  →  → Press  to scroll down units ⇒ Validate with 
Automatic shut-off	2x  →  → Press  to scroll down minutes ⇒ Validate with 
Beep	3x  →  → Press  to activate or deactivate ⇒ Validate with 

Functions available from main screen

(MP 120) Self-calibration	1x  → Start of self-calibration countdown
(MP 120) Velocity activation	1x  →  → Press  to activate or deactivate ⇒ Validate with 
(MP 120) Select air velocity unit	2x  →  → Press  to scroll down units ⇒ Validate with 
(MP 120) Select pressure unit	3x  →  → Press  to scroll down units ⇒ Validate with 
(MP 120) Automatic shut-off	4x  →  → Press  to scroll down units ⇒ Validate with 
(MP 120) Beep	5x  →  → Press  to activate or deactivate ⇒ Validate with 
(MP 120) Ambient Temp.	6x  →  → Enter value with  ⇒ Validate with 
(MP 120) Atmospheric Pressure	7x  →  → Enter value with  ⇒ Validate with 

How to change battery

1. Remove the front part at the back of the instrument
2. Remove old battery
3. Insert the new battery in accordance with proper polarity draw inside the housing.
4. Replace the front.



Once returned to KIMO, required waste collection will be assured in the respect of the environment in accordance to 2002/96/CE guidelines relating to WEEE.

www.kimo.fr

EXPORT DEPARTMENT
Boulevard de Beaubourg - Emerainville - BP 48
77312 MARNE LA VALLEE CEDEX 2
Tel : + 33.1.60.06.69.25 - Fax : + 33.1.60.06.69.29

